

POPCORN MACHINE

7 Easy Steps to Pop the Best Popcorn:

1. Turn all switches "ON"
2. For first batch only, let kettle heat about 4 minutes
3. Add oil or oil bar, then cup of corn with FLAVACOL in it
4. Dump when popping is about 99% completed
5. Repeat step 3 and 4 – always pop at least 5 batches each time you pop
6. Make sure gears engage on top of kettle each time you empty popcorn into bottom of machine
7. On final batch only – turn the kettle heat switch OFF as soon as corn starts popping rapidly (to raise kettle lid)

WARNING! Keep kettle switch "OFF" when not popping.

KEEP MOTOR AND HEAT SWITCH OFF WHEN NOT POPPING CORN.

KEEP DOORS OPEN WHEN POPPING CORN. KEEP DOORS CLOSED WHEN YOU ARE NOT POPPING CORN.